

<b>BBTB Date:</b>	<b>9 December 2019</b>
<b>BBTB Number:</b>	<b>BBTB-043</b>
<b>BBTB Title:</b>	<b>VIGIL RPVS Config Software Update</b>
<b>System Description:</b>	<b>VIGIL 2</b>
<b>Product(s) Affected:</b>	<b>RPVS</b>
<b>Reference:</b>	<b>ECR3882</b>
<b>Priority:</b>	<b>3</b>

---

**1 - Essential:** Action is Recommended

**2 - Important:** Product Form / Fit / Function has been changed (may affect compatibility)

**3 - General:** For information / reference

**4 - Obsolescence:** Notification of Component or Product Obsolescence

---

## DESCRIPTION

Baldwin Boxall has released an updated version of the VIGIL RPVS Config Software V1.03.

## ISSUES FIXED

This updated version of the configuration software displays the correct zone outputs in the “Device Test” window.

There are no other changes to the software.

## **Customer Services Contact Details**

For further assistance with any aspect of this Technical Bulletin please contact:

### **Baldwin Boxall Communications Ltd**

Robbie Trent (Service Manager)

Email: [robbie@baldwinboxall.co.uk](mailto:robbie@baldwinboxall.co.uk)

Ashley Wright (Customer Support Engineer)

Email: [ashley@baldwinboxall.co.uk](mailto:ashley@baldwinboxall.co.uk)

Steve Bladon (Operations Manager)

Email: [steveb@baldwinboxall.co.uk](mailto:steveb@baldwinboxall.co.uk)

Telephone: +44 (0) 1892 664422

Facsimile: +44 (0) 1892 663146