

BBTB Date:	04 April 2022
BBTB Number:	BBTB-081
BBTB Title:	BVRD2M Firmware Update
System Description:	VIGIL2 VA Systems
Product(s) Affected:	BVRD2M
Reference:	ECR4599
Priority:	3

- 1 - Essential:** Action is Recommended
 - 2 - Important:** Product Form / Fit / Function has been changed (may affect compatibility)
 - 3 - General:** For information / reference
 - 4 - Obsolescence:** Notification of Component or Product Obsolescence
-

DESCRIPTION OF THE PROBLEM

Baldwin Boxall has discovered a minor bug with the BVRD2M Front Panel firmware where FT=N was set back to FT=Y if the key was turned back to the “normal” position.

RESOLUTION

The following firmware update has been released: BVRFP V3.2

SUGGESTED ACTION

No immediate action is required as this release is compatible with other module Firmware versions.

Please note however site wide firmware must match (i.e. all BVRD2M units on a given site must run the same firmware). If a replacement unit is supplied or an expansion is performed on an existing site then please ensure the firmware on the new module matches firmware on any existing units.

Customer Services Contact Details

For further assistance with any aspect of this Technical Bulletin please contact:

Baldwin Boxall Communications Ltd

Robbie Trent (Service Manager)

Email: robbie@baldwinboxall.co.uk

Ashley Wright (Customer Support Engineer)

Email: ashley@baldwinboxall.co.uk

Steve Bladon (Operations Manager)

Email: steveb@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422

Facsimile: +44 (0) 1892 663146