

|                             |   |
|-----------------------------|---|
| <b>BBTB Date:</b>           | <b>20 February 2020</b>                         |
| <b>BBTB Number:</b>         | <b>BBTB-046</b>                                 |
| <b>BBTB Title:</b>          | <b>Update BFM BDM Firmware to V2.04</b>         |
| <b>System Description:</b>  | <b>BFM4xx &amp; BDM4xx Microphones</b>          |
| <b>Product(s) Affected:</b> | <b>BFM4xx &amp; BDM4xx Range of Microphones</b> |
| <b>Reference:</b>           | <b>ECR3930</b>                                  |
| <b>Priority:</b>            | <b>3</b>  |

---

**1 - Essential:** Action is Recommended

**2 - Important:** Product Form / Fit / Function has been changed (may affect compatibility)

**3 - General:** For information / reference

**4 - Obsolescence:** Notification of Component or Product Obsolescence

---

## DESCRIPTION

Baldwin Boxall has released an updated version (V2.04) of the firmware used in BFM4xx and BDM4xx ranges of Fire Microphones & Paging Microphones.

## ISSUES FIXED

Bugfix to reduce RS485 bus contention.

### **Customer Services Contact Details**

For further assistance with any aspect of this Technical Bulletin please contact:

#### **Baldwin Boxall Communications Ltd**

Robbie Trent (Service Manager)  
Email: [robbie@baldwinboxall.co.uk](mailto:robbie@baldwinboxall.co.uk)

Ashley Wright (Customer Support Engineer)  
Email: [ashley@baldwinboxall.co.uk](mailto:ashley@baldwinboxall.co.uk)

Steve Bladon (Operations Manager)  
Email: [steveb@baldwinboxall.co.uk](mailto:steveb@baldwinboxall.co.uk)

Telephone: +44 (0) 1892 664422  
Facsimile: +44 (0) 1892 663146