

<b>BBTB Date:</b>	<b>26 November 2021</b>
<b>BBTB Number:</b>	<b>BBTB-074</b>
<b>BBTB Title:</b>	<b>BV3AOM8 Firmware Update</b>
<b>System Description:</b>	<b>Vigil 3 Systems</b>
<b>Product(s) Affected:</b>	<b>BV3AOM8</b>
<b>Reference:</b>	<b>ECR4479</b>
<b>Priority:</b>	<b>2</b>

---

**1 - Essential:** Action is Recommended

**2 - Important:** Product Form / Fit / Function has been changed (may affect compatibility)

**3 - General:** For information / reference

**4 - Obsolescence:** Notification of Component or Product Obsolescence

---

## DESCRIPTION OF THE PROBLEM

Baldwin Boxall has discovered a minor bug with the BV3AOM8 output module relating to Ambient Noise Sensing.

## RESOLUTION

The following firmware updates have been released:

BV3AOM8-ETH\_REV-3137

BV3AOM8-PER\_REV-3146

## SUGGESTED ACTION

No immediate action is required as these releases are compatible with other module Firmware versions.

Please note however site wide firmware must match (i.e. all BV3AOM8 units on a given site must run the same firmware). If a replacement unit is supplied or an expansion is performed on an existing site then please ensure the firmware on the new module matches firmware on any existing units.

## **Customer Services Contact Details**

For further assistance with any aspect of this Technical Bulletin please contact:

### **Baldwin Boxall Communications Ltd**

Robbie Trent (Service Manager)

Email: [robbie@baldwinboxall.co.uk](mailto:robbie@baldwinboxall.co.uk)

Ashley Wright (Customer Support Engineer)

Email: [ashley@baldwinboxall.co.uk](mailto:ashley@baldwinboxall.co.uk)

Steve Bladon (Operations Manager)

Email: [steveb@baldwinboxall.co.uk](mailto:steveb@baldwinboxall.co.uk)

Telephone: +44 (0) 1892 664422

Facsimile: +44 (0) 1892 663146