

BBTB Date:	29 November 2021
BBTB Number:	BBTB-075
BBTB Title:	VIGIL EVAS Config Software Update (V3.02)
System Description:	VIGIL 2
Product(s) Affected:	BVRD2M & BVRD2M4
Reference:	ECR4480
Priority:	3

- 1 - Essential:** Action is Recommended
 - 2 - Important:** Product Form / Fit / Function has been changed (may affect compatibility)
 - 3 - General:** For information / reference
 - 4 - Obsolescence:** Notification of Component or Product Obsolescence
-

DESCRIPTION

Baldwin Boxall has released an updated version (V3.02) of the VIGIL EVAS Config Software (for BVRD2M & BVRD2M4). This update uses installer V1.32.

CHANGE LIST

This updated version of the configuration software allows a greater range of settings for FPI Delay, increasing from 0-99 x 20 seconds to 0-254 x 20 seconds.

COMPATIBILITY

This release is compatible with current BVRD2M4 firmware (V3.06).

This release is compatible with current BVRD2M firmware (BVRDDB V3.06 & BVRFP V3.01).

Please note if a system requires greater than 99 x 20 second FPI Delays (for phased evacuation) please ensure the front panel firmware is V3.01 or greater.

Customer Services Contact Details

For further assistance with any aspect of this Technical Bulletin please contact:

Baldwin Boxall Communications Ltd

Robbie Trent (Service Manager)

Email: robbie@baldwinboxall.co.uk

Ashley Wright (Customer Support Engineer)

Email: ashley@baldwinboxall.co.uk

Steve Bladon (Operations Manager)

Email: steveb@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422