

<b>BBTB Date:</b>	<b>02 December 2022</b>
<b>BBTB Number:</b>	<b>BBTB-084</b>
<b>BBTB Title:</b>	<b>BVMBC Firmware Update</b>
<b>System Description:</b>	<b>VIGIL3 VA Systems</b>
<b>Product(s) Affected:</b>	<b>BVMBC</b>
<b>Reference:</b>	<b>ECR4750</b>
<b>Priority:</b>	<b>3</b>

---

**1 - Essential:** Action is Recommended

**2 - Important:** Product Form / Fit / Function has been changed (may affect compatibility)

**3 - General:** For information / reference

**4 - Obsolescence:** Notification of Component or Product Obsolescence

---

## DESCRIPTION OF THE PROBLEM

Baldwin Boxall has released new firmware to support an alternative current sensing IC.

## RESOLUTION

Firmware release of BVMBC\_REV-3279

## SUGGESTED ACTION

No action required.

Baldwin Boxall does not recommend attempting to update existing installations with this version. The release detailed in this Technical Bulletin is a fix related to specific conditions or components and is not a feature release.

Existing sites will already have bespoke configuration and all relevant features and functions will have been tested to ensure correct operation.

## **Customer Services Contact Details**

For further assistance with any aspect of this Technical Bulletin please contact:

### **Baldwin Boxall Communications Ltd**

Robbie Trent (Service Manager)

Email: [robbie@baldwinboxall.co.uk](mailto:robbie@baldwinboxall.co.uk)

Ashley Wright (Customer Support Engineer)

Email: [ashley@baldwinboxall.co.uk](mailto:ashley@baldwinboxall.co.uk)

Steve Bladon (Operations Manager)

Email: [steveb@baldwinboxall.co.uk](mailto:steveb@baldwinboxall.co.uk)

Telephone: +44 (0) 1892 664422

Facsimile: +44 (0) 1892 663146