

TECHNICAL BULLETIN

23 May 2024
BBTB-116
Change to optional supply of glazed rack doors
VA / PA Rack Systems
RK6U - RK47U Rack Systems
ECR5502
2

I - Essential: Action is Recommended

- 2 Important: Product Form / Fit / Function has been changed (may affect compatibility)
- 3 General: For information / reference

4 - Obsolescence: Notification of Component or Product Obsolescence

DESCRIPTION OF CHANGE

Historically Baldwin Boxall have always included by default a chargeable glazed door in all quotes for assembled RK6U - RK47U Rack Systems.

Following a review of customer feedback and as part of our sustainability objectives we have changed our policy and all new quotes created after **1st June 2024** will no longer include a glazed door by default. The glazed door will instead be offered as an optional chargeable component part that should be selected if required.

REASON FOR CHANGE

Baldwin Boxall constantly reviews activities to ensure the best possible customer service is provided, while minimising our environmental impact. These are key factors of both our ISO9001 & ISO14001 approvals and this change is an opportunity to ensure equipment supplied is not only fit for purpose & compliant with applicable legislation but also supports our sustainability objectives.

> Information not to be copied or disclosed without written permission Copyright Baldwin Boxall Communications Limited COMMERCIAL IN CONFIDENCE



TECHNICAL BULLETIN

Technical Support Contact Details

For further assistance with any aspect of this Technical Bulletin please contact:

Baldwin Boxall Communications Ltd

After Sales Technical Support Email: technicalsupport@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422 and select option 2

Information not to be copied or disclosed without written permission Copyright Baldwin Boxall Communications Limited COMMERCIAL IN CONFIDENCE