

BBTB Date:	2 July 2019
BBTB Number:	BBTB-023
BBTB Title:	Vigil25 Support End Date
System Description:	Vigil25 Support End Date - 1st Oct 2012
Product(s) Affected:	BV6060 / BV150 / BV333 & BVPS
Reference:	N/A
Priority:	4

1 - Essential: Action is Recommended

2 - Important: Product Form / Fit / Function has been changed (may affect compatibility)

3 - General: For information / reference

4 - Obsolescence: Notification of Component or Product Obsolescence

DESCRIPTION

The Vigil25 range of amplifiers (BV6060, BV150, BV333) & BVPS power supply were manufactured between 1996 and 2002.

We can confirm that due to component obsolescence we can no longer offer service support for these products as the support end date was **1st October 2012**. Please be aware that these products may not be repairable should they fail.

COMPATIBILITY

It is possible to replace individual items (with some additional site wiring) as follows:

BV6060 > BV125D

BV150 > (depending on load) either BV125D or BV225

BV333 > 2 x BV225 & BVSMPS (PSU / Charger)

BVPS > BVSMPS

Due to these products no longer being supported Baldwin Boxall suggests consideration / risk assessments are carried out at any sites that utilise these VIGIL25 modules with a view to upgrading these systems to ensure continued system operation.

We would welcome the opportunity to discuss this with you in more detail.

If you require any further information please feel free to contact us.

Customer Services Contact Details

For further assistance with any aspect of this Technical Bulletin please contact:

Baldwin Boxall Communications Ltd

Robbie Trent (Service Manager)

Email: robbie@baldwinboxall.co.uk

Ashley Wright (Customer Support Engineer)

Email: ashley@baldwinboxall.co.uk

Steve Bladon (Operations Manager)

Email: steveb@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422

Facsimile: +44 (0) 1892 663146