

TECHNICAL BULLETIN

BBTB Date:	20 August 2020
BBTB Number:	ВВТВ-053
BBTB Title:	BVRDAUSnnRM Firmware Update V2.09
System Description:	VIGIL 2
Product(s) Affected:	BVRDAUSnnRM all variants
Reference:	ECR4044
Priority:	2

- I Essential: Action is Recommended
- 2 Important: Product Form / Fit / Function has been changed (may affect compatibility)
- 3 General: For information / reference
- 4 Obsolescence: Notification of Component or Product Obsolescence

DESCRIPTION

Baldwin Boxall has released updated VIGIL BVRDAUSnnRM firmware V2.09.

Added Features or Fixes

The updated firmware includes bugfixes that were only evident if multiple BVRDAUSnnRM microphones were connected to a single BVRDAUS2M router.

COMPATIBILITY

This firmware is compatible with the current version of Configuration Software (V2.09).

Baldwin Boxall recommends all networked equipment uses identical versions of firmware.



TECHNICAL BULLETIN

Customer Services Contact Details

For further assistance with any aspect of this Technical Bulletin please contact:

Baldwin Boxall Communications Ltd

Robbie Trent (Service Manager) Email: robbie@baldwinboxall.co.uk

Ashley Wright (Customer Support Engineer) Email: ashley@baldwinboxall.co.uk

Steve Bladon (Operations Manager) Email: steveb@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422 Facsimile: +44 (0) 1892 663146

> Information not to be copied or disclosed without written permission Copyright Baldwin Boxall Communications Limited COMMERCIAL IN CONFIDENCE