

BBTB Date:	13 March 2023
BBTB Number:	BBTB-086
BBTB Title:	OmniCare PLUS PC Software Update V1.4
System Description:	OmniCare PLUS Systems
Product(s) Affected:	BVOCTSB / BVOCTSG
Reference:	ECR4642
Priority:	3

- 1 - **Essential:** Action is Recommended
 - 2 - **Important:** Product Form / Fit / Function has been changed (may affect compatibility)
 - 3 - **General:** For information / reference
 - 4 - **Obsolescence:** Notification of Component or Product Obsolescence
-

DESCRIPTION OF THE PROBLEM

Baldwin Boxall has identified a bug when adding consoles in Admin mode where they can exceed the boundaries of the screen.

RESOLUTION

The software has now been updated to V1.4 and consoles are added in columns of 10 to prevent them falling off the screen.

SUGGESTED ACTION

Baldwin Boxall does not recommend attempting to update existing installations with these versions. The releases detailed in this Technical Bulletin are bugfixes related to specific configurations and are not feature releases.

Existing sites will already have bespoke configuration and all relevant features and functions will have been tested to ensure correct operation.

Technical Support Contact Details

For further assistance with any aspect of this Technical Bulletin please contact:

Baldwin Boxall Communications Ltd

After Sales Technical Support

Email: technicalsupport@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422 and select option 3