

## **TECHNICAL BULLETIN**

BBTB Date: 16 September 2022

BBTB Number: BBTB-090

BBTB Title: BVPM Support End Date May 2022

System Description: VIGIL2

Product(s) Affected: BVPM

Reference: ECR4795

Priority: 4

I - Essential: Action is Recommended

2 - Important: Product Form / Fit / Function has been changed (may affect compatibility)

**3 - General:** For information / reference

4 - Obsolescence: Notification of Component or Product Obsolescence

## **OBSOLESCENCE STATEMENT**

The BVPM mains only VIGIL2 power supply was manufactured between October 1997 and May 2012 and was superseded in May 2012 by the BVSMPM.

### END OF SERVICE SUPPORT

We can now confirm that as of 1st May 2022 we can longer provide service support for this product.

### SUGGESTED ALTERNATIVE PRODUCT

The BVSMPM is the best fit replacement product that is backwards compatible with the BVPM for the majority of installations.

If you require any further information please feel free to contact us.

#### **Customer Services Contact Details**

Information not to be copied or disclosed without written permission Copyright Baldwin Boxall Communications Limited COMMERCIAL IN CONFIDENCE



# **TECHNICAL BULLETIN**

For further assistance with any aspect of this Technical Bulletin please contact:

#### **Baldwin Boxall Communications Ltd**

Robbie Trent (Service Manager) Email: robbie@baldwinboxall.co.uk

Ashley Wright (Customer Support Engineer)

Email: ashley@baldwinboxall.co.uk

Steve Bladon (Operations Manager) Email: steveb@baldwinboxall.co.uk

Telephone: +44 (0) 1892 664422 Facsimile: +44 (0) 1892 663146